



- SONDE 1 +5 (P1 21C)
- SONDE 2 +5 (P1 22C)
- SONDE 3 +5 (P1 23C)
- SONDE 4 +5 (P1 24C)
- DVM GND (P1 10C)
- SONDE 1 S1 (P1 11C)
- DVM S1 (P1 11A)
- SONDE 2 S2 (P1 12C)
- DVM S2 (P1 12A)
- SONDE 3 S3 (P1 13C)
- DVM S3 (P1 13A)
- SONDE 4 S4 (P1 14C)
- DVM S4 (P1 14A)
- SONDE 1 S11 (P1 26C)
- DVM S11 (P1 26A)
- SONDE 2 S12 (P1 27C)
- DVM S12 (P1 27A)
- SONDE 3 S13 (P1 28C)
- DVM S13 (P1 28A)
- SONDE 4 S14 (P1 29C)
- DVM S14 (P1 29A)
- GND OUT- (P1 9A)
- SONDE PT100 OUT+ (P1 8A)

R12	Observations :	AD590.SCH	Appareil No: 061088	A3
C3	Modifications:	Sheet No:		
	ADAPTATEUR AD590+PT100	Ech.	Dessine R. Crausaz	
	AD590	Date	06.10.1988	
	THERMOMETRE	Etude	R. Crausaz	
		Revise	27.09.1991	
	OBSERVATOIRE DE GENEVE Tel. (022) 755.26.11	LE-IN-2E-B0731		